

End of Life Notice

Dear Partners:

ATOP appreciates your daily support on Fiber Optics communication business. We would like to notify you that the models below mentioned are discontinued due to component End-of-Life

Phase-out Transceiver

SFP-T1 SFP to RJ45 Transceiver, 10/100Mbps, $0\sim70^{\circ}\text{C}$ ASFPT-T1-I SFP to RJ45 Transceiver, 1000Mbps, LOS-Enable, $-40\sim85^{\circ}\text{C}$ ASFPT-T3-I SFP to RJ45 Transceiver, 10/100/1000Mbps auto-negotiation, LOS-Enable, $-40\sim85^{\circ}\text{C}$ LS38-H3S-TI-N-EX SFP Transceiver, 10 Gbps Single-mode 1311 nm, DFB, 3.3 V,TTL, (10 km), $-40^{\circ}\text{C} \sim 85^{\circ}\text{C}$ LS48-H3L-TI-N SFP Transceiver, 10 Gbps Single-mode 1550 nm, EML, 3.3 V, TTL, (40 km), $-40^{\circ}\text{C} \sim 85^{\circ}\text{C}$ LS48-H3U-TI-N SFP Transceiver, 10 Gbps Single-mode 1550 nm, EML, 3.3 V, TTL, (80 km), $-40^{\circ}\text{C} \sim 85^{\circ}\text{C}$

We suggest the replacement models as the following:

EoL Product	EoL Part Number	Replacement Product	Release	Repl. Part Number	Last order Date
ASFPT-T1-I ASFPT-T3-I LS38-H3S-TI-N-EX LS48-H3L-TI-N LS48-H3U-TI-N SFP-T1	522ASFPTT1I001G 522ASFPTT3I001G 50710071G 50710081G 50710091G 522SFPT1000001G	FCLF8522P2BTL FCLF8522P2BTL LE38-H3S-TI-N LE48-H3L-TI-N N/A 522SFP8008l0001G	released released released released n/a released		
					6/30/2019
			= E>		

Phase out reason : Component End-of-Life

However, please do not hesitate to contact us if you have any further comments.

The following manufacturer/importer is responsible for this declaration:

Company's Name:

Atop Technologies, Inc.

Company's Address:

2F, No 146, Sec. 1, Tung-Hsing Rd., Jubei, Hsinchu 30261, TAIWAN, R.O.C

This declaration has been released under the responsibility of

Name:

Matteo Tabarelli de Fatis

Title:

Product Manager Hsinchu, Taiwan

Place: Date:

30-Apr-19

www.atop.com.tw